

Inspection Photos

9/10/2020

Operator: TEP ROCKY MOUNTAIN LLC -
96850

Location ID: 324181
Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 324181



Photo 1: Photo taken from the south end of the Location, facing north. Photo shows large areas of the location is not progressing towards reclamation requirements.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 324181



Photo 2: Photo taken from the Location. Photo shows location is not progressing towards uniform perennial vegetative establishment reflective of the reference. Photo also show Chicory plants on Location; This is a Colorado State listed noxious weed.



Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 324181



Photo 3: Photo taken from the north end of the Location, facing south. Photo shows an individual Takarisk plant on Location. This is a Colorado State listed noxious weed.



Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 324181



Photo 4: Photo taken from the access road, racing north. Photo shows areas of the access road disturbance that is not progressing towards reclamation requirements.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 324181



Photo 5: Photo shows vegetation on the adjacent reference area. Location/access road is not reflective of the reference.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 324181



Photo 6: 2014 Google Earth aerial imagery. Photo shows Location and access road disturbance