

Inspection Photos

Location Name: WAGNER-67N64W /30NWSW

Location #: 310319



Colorado Oil & Gas Conservation Commission
40.5415, -104.59959, 4803.4ft, 334°
09/11/2020 11:37:08

Photo #1

Wagner 30-32 (05-123-26227) Wellsite

Producing | PR



Colorado Oil & Gas Conservation Commission
40.54035, -104.59279, 4784.9ft, 229°
09/11/2020 12:53:32

Photo #2

Wilhite 30-34, Wagner 30-32 Battery site

Active

Formerly served:

Wilhite 30-31, Wagner 30-33, 30-35

Plugged & Abandoned | PA

Inspection Photos

Location Name: WAGNER-67N64W /30NWSW

Location #: 310319



Photo #3

Wagner 30-32, Wilhite 30-34 Battery site

*Unused Equipment: Tubing
prior insp.*



Photo #4

Wilhite 30-34, Wagner 30-32 Battery site

**Unused Equipment: Tubing
Removed
Verified by walk around**