

BP L48 San Juan



V2 Compliance Follow Up Form

18154263287

Reference Number:	20200908-18154263287
Form Name:	V2 Compliance Follow Up Form
Submitter Name:	Cole Nichols (colen@horizonenvservices.com) colen@horizonenvservices.com
Submission Date:	Sep 8, 2020 9:01:44 AM MDT
Location:	91 S Skylane Dr, Durango, CO 81303, USA Sep 8, 2020 9:01:09 AM MDT [View Map]

INFORMATION

Section 1

Name	colen@horizonenvservices.com
Date	Sep 4, 2020
Well Name	HUNGERFORD GAS UNIT A 1
API Number	50670759500
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Clean Up Weed Debris
Photo of first corrective action completed	



**Completed work description Corrective
Action 1**

Before removal of weed debris.

Photo of second corrective action completed



Completed work description of corrective action 2

Removed weed debris on location.

Photo of third corrective action completed



Completed work description of corrective action 3

Removed weed debris on location.

Photo of fourth corrective action completed



Completed work description

Removed weed debris on location.

Completed work description of corrective action 4

Removed weed debris on location.

Additional photos



Additional photos



Completed work description
Summary of all work completed

Removed weed debris on location.
Previous treatment dates 7/11/2016, 7,27/2017,
7/27/2018, 5/2/2019, 6/2/2020