

Inspection Photos

API#107-06241

Operator: Bluestone

Insp#: 692402477

Insp Date: 8/26/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location from entry to South.

August 26, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Bluestone PA Pritlaw Partners API#107-06241



Photo#2:

B List Noxious Weeds are established on site; Houndstongue, Toadflax, Musk and Bull thistle.

August 26, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Bluestone PA Pritlaw Partners API#107-06241



Photo#3:

Perennial grasses are established across the site. Note Houndstongue rosette in foreground; insert of developing erosion concern.

August 26, 2020



Photo#4:
Gates down at entry. Arrow at point where cattle guard must have been installed before removal.



Photo#5:
Cattle guard and base stored on site; insert of sign set in ground in revegetated area.

August 26, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Bluestone PA Pritlaw Partners API#107-06241