

Inspection Photos  
Location Name: AC 17-14  
Location ID: 307377



**Photo 1 gabion basket full of sediment not properly maintained allowing sediment from road way to go into Big Bingham canyon water way.**



**Inspection Photos**  
**Location Name: AC 17-14**  
**Location ID: 307377**



**Photo 3 road between Big bingham entrance and AC 17-14 not properly maintained bar ditch full of sediment causing storm water to cross road and go into Big Bingham water way**



**Photo 4 Reel caused by storm water crossing road in Pic 3.**



**Inspection Photos**  
**Location Name: AC 17-14**  
**Location ID: 307377**



**Photo 5 Road between big Bingham entrance and AC 17-14 not properly maintained. Drainage from hillside causing sediment to build up on road way.**



**Photo 6 culvert in pic 5 is plugged on outlet side in creek**



**Inspection Photos**  
**Location Name: AC 17-14**  
**Location ID: 307377**



**Photo 7 Meter house: no calibration card in meter box.**



**Photo 8 Weeds on location and around equipment.**



**Inspection Photos**  
**Location Name: AC 17-14**  
**Location ID: 307377**



**Photo 9 Weeds and risers on location not LOTO.**



**Photo 10 1" risers in liquid ring sound walls not LOTO**

**Inspection Photos**  
**Location Name: AC 17-14**  
**Location ID: 307377**



**Photo 11 Stained soil around liquid ring.**