

Inspection Photos
Location Name: AC 13-15
Location ID: 308031



Photo 1 location sign. Risers not LOTO unused equipment separator house due to well being TA



Photo 2 Unused equipment PU and risers not LOTO