

Inspection Photos

API# 081-07681

Operator: GRMR

Insp#: 692402487

Insp Date: 8/27/2020



Photo#1:
View of Location to Southeast.

Photo#2:
View of Location to Northwest.

August 27, 2020



Photo#2:

B List Noxious weeds, Houndstongue, Musk thistle.

August 27, 2020



Inspection Photos: GRMR PA Hart Gulch API #081-07681



Photo#3:
Dense establishment of curly cup gumweed.



Photo#4:
Dense establishment of curly cup gumweed

August 27, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: GRMR PA Hart Gulch API #081-07681



Photo#5:
Areas where vegetation growth is more sparse.



Photo#6:
Areas where vegetation growth is more sparse

August 27, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: GRMR PA Hart Gulch API #081-07681