

Inspection Photos
Location Name: APACHE CANYON 03-01
API#: 05-071-07961
INSP. #: 695103277



Colorado Oil & Gas Conservation Commission
37.11704, -104.97551, 2413.0m, 263°
2020/09/13 13:23:53

PHOTO 1: LOCATION



Colorado Oil & Gas Conservation Commission
37.11722, -104.97559, 2387.0m, 238°
2020/09/13 13:24:43

PHOTO 2: WELL SIGN

Inspection Photos

Location Name: APACHE CANYON 03-01

API#: 05-071-07961

INSP. #: 695103277



**PHOTO 3: TRASH IN METER HOUSE AND ON LOCATION.
COMPLY WITH RULE 603.f. CA DATE 10-13-20.**



**PHOTO 4: UNUSED RISERS. REMOVE RISERS COMPLY WITH
603.F. (UNUSED EQUIPMENT). CA DATE 10-13-20.**

Inspection Photos

Location Name: APACHE CANYON 03-01

API#: 05-071-07961

INSP. #: 695103277



PHOTO 5: UNUSED RISERS. REMOVE RISERS COMPLY WITH 603.F. (UNUSED EQUIPMENT), CA DATE 10-13-20.



PHOTO 6: UNUSED EQUIPMENT. REMOVE UNUSED EQUIPMENT COMPLY WITH 603.F. (UNUSED EQUIPMENT), CA DATE 10-13-20.

Inspection Photos

Location Name: APACHE CANYON 03-01

API#: 05-071-07961

INSP. #: 695103277



PHOTO 7: TRASH ON LOCATION. REMOVE TRASH COMPLY WITH 603.F. CA DATE 10-13-20.



PHOTO 8: UNUSED EQUIPMENT. REMOVE UNUSED EQUIPMENT COMPLY WITH 603.F. (UNUSED EQUIPMENT). CA DATE 10-13-20.

Inspection Photos
Location Name: APACHE CANYON 03-01
API#: 05-071-07961
INSP. #: 695103277



PHOTO 9: TRASH OR DEBREE. REMOVE TRASH COMPLY WITH 603.F. . CA DATE 10-13-20.



PHOTO 10: UNUSED EQUIPMENT. REMOVE UNUSED EQUIPMENT COMPLY WITH 603.F. CA DATE 10-13-20.

Inspection Photos

Location Name: APACHE CANYON 03-01

API#: 05-071-07961

INSP. #: 695103277



PHOTO 11: UNUSED EQUIPMENT. REMOVE UNUSED EQUIPMENT COMPLY WITH 603.F. CA DATE 10-13-20.



PHOTO 12: UNUSED EQUIPMENT. REMOVE UNUSED EQUIPMENT COMPLY WITH 603.F. CA DATE 10-13-20.

Inspection Photos

Location Name: APACHE CANYON 03-01

API#: 05-071-07961

INSP. #: 695103277



PHOTO 13: UNUSED EQUIPMENT. REMOVE UNUSED EQUIPMENT COMPLY WITH 603.F. CA DATE 10-13-20.



PHOTO 14: TRASH OR DEBREE. REMOVE TRASH OR DEBREE COMPLY WITH 603.F. CA DATE 10-13-20.

Inspection Photos

Location Name: APACHE CANYON 03-01

API#: 05-071-07961

INSP. #: 695103277



PHOTO 15: UNUSED EQUIPMENT (RISER). REMOVE UNUSED EQUIPMENT COMPLY WITH 603.F. CA DATE 10-13-20.



PHOTO 16. UNUSED EQUIPEMNT STORED ON LOCATION. REMOVE UNUSED EQUIPMENT COMPLY WITH 603.F. CA DATE 10-13-20.



Inspection Photos

Location Name: APACHE CANYON 03-01

API#: 05-071-07961

INSP. #: 695103277



PHOTO 17: UNUSED EQUIPMENT . REMOVE UNUSED EQUIPMENT COMPLY WITH 603.F. CA DATE 10-13-20.



PHOTO 18: TRASH OR DEBREE. REMOVE TRASH OR DEBREE COMPLY WITH 603.F. CA DATE 10-13-20.

Inspection Photos

Location Name: APACHE CANYON 03-01

API#: 05-071-07961

INSP. #: 695103277



PHOTO 19: UNUSED EQUIPMENT . REMOVE UNUSED EQUIPMENT COMPLY WITH 603.F. CA DATE 10-13-20.



PHOTO 20: TRASH OR DEBREE. REMOVE TRASH OR DEBREE COMPLY WITH 603.F. CA DATE 10-13-20.

