

Inspection Photos
Location Name: Smith Rancho 1-14
Location ID: 316751



Photo 1. Overview of location taken facing west.



Inspection Photos
Location Name: Smith Rancho 1-14
Location ID: 316751



Photo 2. Stained soil at wellhead.



Photo 3. Stained soil at pump jack motor.

Inspection Photos
Location Name: Smith Rancho 1-14
Location ID: 316751



Photo 4. Tank labels faded and peeling.



Photo 5. Gravel stored on location.