

Inspection Photos

API: 071-08053

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 9/16/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-08053 | Date: 9/16/2020

Inspection Photos



Photo 1. Facing north along the access road which has not been recontoured and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08053 | Date: 9/16/2020

Inspection Photos



Photo 2. Facing southwest along the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08053 | Date: 9/16/2020

Inspection Photos



Photo 3. Facing northeast along the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08053 | Date: 9/16/2020

Inspection Photos



Photo 4. Facing north toward the location. The location has not been recontoured and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08053 | Date: 9/16/2020

Inspection Photos



Photo 5. The location has not been recontoured and vegetation has not adequately established.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08053 | Date: 9/16/2020

Inspection Photos



Photo 6. Facing southwest toward the location.



Inspection Photos



Photo 7. Facing south toward the fill slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08053 | Date: 9/16/2020

Inspection Photos



Photo 8. Facing east toward the surrounding undisturbed reference area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08053 | Date: 9/16/2020