

Inspection Photos

API#107-06201

Operator: North Finn

Insp#: 692402517

Insp Date: 9/16/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:

View at entry into location; insert is Anchor pile at east side of entry.

September 16, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: North Finn PA Breeze API#107-06201



Photo#2:
View South over Location and site fencing.

September 16, 2020



Photo#3:
View of Location vegetation.

September 16, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: North Finn PA Breeze API#107-06201