

# *Inspection Photos*

*API#107-06127*

*Operator: Antelope Energy*

*Insp#: 692402516*

*Insp Date: 9/16/20*





Photo#1:  
Overview of Location to Northeast.

September 16, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Antelope Energy State of Co API#107-06127



Photo#2:  
View of ongoing reclamation work at site.

September 16, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Antelope Energy State of Co API#107-06127



Photo#3:  
Stained material seen on Location.



Photo#4  
Stained Material seen on Location.

September 16, 2020