

Inspection Photos

PIT ID:256456

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 9/16/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

256456 | Date: 9/16/2020

Inspection Photos



Photo 1. Facing northeast toward the reclaimed pit location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

256456 | Date: 9/16/2020

Inspection Photos



Photo 2. Facing northeast toward the reclaimed pit location. The vegetation observed at the location was Alfalfa, Orchard grass, Yellow clover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

256456 | Date: 9/16/2020

Inspection Photos



Photo 3. Facing northeast toward the reclaimed pit location. Vegetation has not yet established to 80%. Additional growing seasons and reseeding may need to be performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

256456 | Date: 9/16/2020

Inspection Photos



Photo 4. Facing southwest toward the undisturbed area which consists of native vegetation such as Blue grama, Sand dropseed, Western wheat.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

256456 | Date: 9/16/2020