

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/17/2020

Submitted Date:

09/22/2020

Document Number:

688800807**FIELD INSPECTION FORM**Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
Hughes, Jim _____ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 1199 MAIN AVENUE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	SW Inspection Reports
Heil, John		john.heil@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	
Inspections, All		SanJuanCOGCC@bp.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
478046	SPILL OR RELEASE	AC	09/16/2020		-	High Flume Canyon	EI

General Comment:

On September 17, 2020 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Spill/Release Point ID #478046. For more information regarding this release, please refer to document #402490497.

Environmental**Spills/Releases:**

Type of Spill: PRODUCED WATER

Estimated Spill Volume: _____

Comment: [Please refer to Initial Spill/Release Report Document #402490497 for more information regarding this release. Updated coordinates received via email from the operator.](#)Corrective Action: [Control and contain spills/releases and clean up per Rule 906.a.](#)

Date: 10/22/2020

Reportable: YES

GPS: Lat 37.096514

Long -107.902670

Proximity to Surface Water:

Depth to Ground Water:

Water Well Complaint:

Lat

Long

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

COGCC Comments

Comment	User	Date
On September 17, 2020 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Spill/Release Point ID #478046. For more information regarding this release, please refer to document #402490497. According to the COGIS database, a 4" carbon steel produced water gathering line follows High Flume Canyon Road in this area. During this inspection, wet and stained soil was observed along the east side of the county road.	hughesjo	09/22/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800808	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5253245