

Inspection Photos
Location Name: Dunn 1-21 Pad
Location ID: 444643



Photo 1: Wellheads



Photo 2: Tank not grounded

Inspection Photos
Location Name: Dunn 1-21 Pad
Location ID: 444643



Photo 3: Unused fencing