

Inspection Photos
Location Name: RSU-Anschutz 4-61-4 NW
Location ID: 454815



Photo 1 – Stained Soil at Wellheads, Locate Flags



Photo 2 – West Wellheads

Inspection Photos
Location Name: RSU-Anschutz 4-61-4 NW
Location ID: 454815



Photo 3 – 4-61-04-2525C Wellhead



Photo 4 – West Wellheads, Stained Soil

Inspection Photos
Location Name: RSU-Anschutz 4-61-4 NW
Location ID: 454815



Photo 5 – East Wellheads, Stained Soil



Photo 6 – East Wellheads

Inspection Photos
Location Name: RSU-Anschutz 4-61-4 NW
Location ID: 454815



Photo 7 – Separators, VRTs, Gas Meters



Photo 8 – Tank Battery

Inspection Photos
Location Name: RSU-Anschutz 4-61-4 NW
Location ID: 454815



Photo 9 – Tank Battery Sign



Photo 10 – Unmarked Risers at VRUs

Inspection Photos
Location Name: RSU-Anschutz 4-61-4 NW
Location ID: 454815



Photo 11 – Unmarked Risers at Horizontal Separator



Photo 12 – Locate Flags no longer in use