

Inspection Photos
Location Name: State Pronghorn V-32 PAD
Location ID: 438730



Photo 1 – Signs at Entrance



Photo 2 – Wellhead

Inspection Photos
Location Name: State Pronghorn V-32 PAD
Location ID: 438730



Photo 3 – Wellheads



Photo 4 – Separators

Inspection Photos
Location Name: State Pronghorn V-32 PAD
Location ID: 438730



Photo 5 – 60 BBL Missing NFPA Label




Photo 6 – Gas Lift Meter Shed and Maintenance Tank

Inspection Photos
Location Name: State Pronghorn V-32 PAD
Location ID: 438730




Photo 7 – Unmarked Risers North of Compressor




Photo 8 – Drain Pit missing Content, Capacity and NFPA Labels

Inspection Photos
Location Name: State Pronghorn V-32 PAD
Location ID: 438730




Photo 9 – Unmarked Risers North of Compressor, Drain Pit missing Content, Capacity and NFPA Labels




Photo 10 – Unmarked Risers