

Inspection Photos

API: 05-025-06020

Operator: CRAZY 8 ENERGY LLC

Inspection Date: 9/23/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-025-06020 | Date: 9/23/2020

Inspection Photos



Photo 1. Facing west toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-025-06020 | Date: 9/23/2020

Inspection Photos



Photo 2. Facing southwest toward the location. The location has not been reclaimed. There are weeds and bare soil throughout the site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-025-06020 | Date: 9/23/2020

Inspection Photos



Photo 3. The diversion ditch at the north side of the location has not been recontoured. Arrow points to 4.5 ft. shovel placed in ditch.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-025-06020 | Date: 9/23/2020

Inspection Photos



Photo 4. Facing southwest toward the location. The location has not been reclaimed. There are weeds and bare soil throughout the site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-025-06020 | Date: 9/23/2020

Inspection Photos



Photo 5. Facing east toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-025-06020 | Date: 9/23/2020

Inspection Photos



Photo 6. Facing north toward the location. The location has not been reclaimed. There are weeds and bare soil throughout the site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-025-06020 | Date: 9/23/2020

Inspection Photos



Photo 7. There is liner debris observed throughout areas of the location. A piece of cement debris was observed. All debris needs to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-025-06020 | Date: 9/23/2020

Inspection Photos



Photo 8. Center of the location facing west. There is undesirable weeds (Kochia sp., Sal sp.) observed throughout the location. Arrow points to 4.5 ft. shovel to shows size of weeds.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-025-06020 | Date: 9/23/2020