

## Inspection Photos

Location Name: SG INTERESTS I LTD PASCO SPADAFORA #2 /413893

Location ID: 413893



Photo #1919 from NE corner of location.



Photo #1920 Multiple places with debris encroaching on tank containments.

## Inspection Photos

Location Name: SG INTERESTS I LTD PASCO SPADAFORA #2 /413893

Location ID: 413893



**Photo #1923 Multiple places with debris encroaching on tank containments.**



**Photo #1924 Multiple places with debris encroaching on tank containments.**