

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402498643

Date Received:  
09/28/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
.		<u>NBL_DJBU_Inspections@NBLENERGY.COM</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 699102359

Inspection Date: 09/10/2020

FIR Submit Date: 09/10/2020

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: NOBLE ENERGY INC

Company Number: 100322

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

LOCATION - Location ID: 438698

Location Name: Higgins Number: D19-720 County: \_\_\_\_\_  
Multi

Qtrqtr: NENE Sec: 19 Twp: 3N Range: 64W Meridian: 6

Latitude: 40.216950 Longitude: -104.585870

FACILITY - API Number: 05-123-00 Facility ID: 438698

Facility Name: Higgins Number: D19-720  
Multi

Qtrqtr: NENE Sec: 19 Twp: 3N Range: 64W Meridian: 6

Latitude: 40.216950 Longitude: -104.585870

CORRECTIVE ACTIIONS:

1  CA# 141817

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 10/02/2020

Response: CA COMPLETED

Date of Completion: 09/21/2020

Operator Comment: Noble has ensured all fittings have been fastened securely.

COGCC Decision: **Not Approved**

COGCC Representative: Inspection response to FIRR is not approved due to it leaking from the threads on the bull plug

2  CA# 141818

Corrective Action: "Properly dispose of oily waste in accordance with 907.e." Date: 10/02/2020

Response: CA COMPLETED Date of Completion: 09/21/2020

Operator Comment: Noble energy has removed and properly disposed of the stained soil.

COGCC Decision: **Not Approved**

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tesla Dougherty Signed:

Title: EHS Specilist Date: 9/28/2020 12:08:55 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402498643	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files