



40.20101, -107.47344, 8026.0ft, 17°  
09/28/2020 01:42:23 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 1. Location.**

**Seely Land & Livestock 1      API: 05-103-09250**  
**Inspection: 700403639**





40.20102, -107.47321, 8020.6ft, 347°  
09/28/2020 01:42:45 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 2. Pump jack.**

**Seely Land & Livestock 1      API: 05-103-09250**  
**Inspection: 700403639**





40.20124, -107.47313, 8021.8ft, 296°  
09/28/2020 01:45:25 PM









40.20144, -107.47295, 8016.7ft, 28°  
09/28/2020 01:48:06 PM









**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 7. Chemical containers.**

**Seely Land & Livestock 1     API: 05-103-09250**  
**Inspection: 700403639**





**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 8. Unused equipment stored next to propane tanks.**

**Seely Land & Livestock 1      API: 05-103-09250**  
**Inspection: 700403639**









40.20123, -107.47323, 8023.1ft, 240°  
09/28/2020 01:44:01 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 10. Side of pump jack.**

**Seely Land & Livestock 1      API: 05-103-09250**  
**Inspection: 700403639**



