

Inspection Photos
Location Name: Kettler 1-18
Location ID: 322621



Photo 1: Wellhead Sign



Photo 2: Weeds removed

Inspection Photos
Location Name: Kettler 1-18
Location ID: 322621



Photo 3: Fencing repaired



Photo 4: Holes in berm wall

Inspection Photos
Location Name: Kettler 1-18
Location ID: 322621



Photo 5: Hole in berm wall



Photo 6: Weeds