

Inspection Photos

Location Name: Gibson Gulch Unit 66S91W 29SWSW & Tank Battery Spill Location ID: #323972
& Spill/Release ID: 466240 REM 14050
Inspection Date: September 30, 2020



Facility sign.

Excavation app 30'x 20' by app 8' depth. Monitoring well in right of photo. Note the abundance of weeds.



Inspection Photos

Location Name: Gibson Gulch Unit 66S91W 29SWSW & Tank Battery Spill Location ID: #323972
& Spill/Release ID: 466240 REM 14050

Inspection Date: September 30, 2020



Monitoring well in center of photo. Note the abundance of weeds.

Flow line LOTO.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Gibson Gulch Unit 66S91W 29SWSW & Tank Battery Spill Location ID: #323972 &

Spill/Release ID: 466240 REM 14050

Inspection Date: September 30, 2020



Flow lines throughout excavation.



View looking easterly.

Inspection Photos

Location Name: Gibson Gulch Unit 66S91W 29SWSW & Tank Battery Spill Location ID: #323972
& Spill/Release ID: 466240 REM 14050
Inspection Date: September 30, 2020



Evidence of surface water run on into excavation.



Tank and unused equipment adjacent to the well head.



Inspection Photos

Location Name: Gibson Gulch Unit 66S91W 29SWSW & Tank Battery Spill Location ID: #323972
& Spill/Release ID: 466240 REM 14050

Inspection Date: September 30, 2020



Well head sign.



Well LOTO.



Inspection Photos

Location Name: Gibson Gulch Unit 66S91W 29SWSW & Tank Battery Spill Location ID: #323972
& Spill/Release ID: 466240 REM 14050

Inspection Date: September 30, 2020



Tank open to the atmosphere.



Tank LOTO.

