

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/30/2020

Submitted Date:

10/03/2020

Document Number:

701001448

**FIELD INSPECTION FORM**

Loc ID 311097 Inspector Name: Welsh, Brian On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10730  
Name of Operator: CWC PETRO LLC  
Address: 6957 #A ISABELL LN  
City: ARVADA State: CO Zip: 80007

**Findings:**

- 10 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Clark, Christopher	(303) 519-7870	cwclark@cwcpetro.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
298821	WELL	PR	06/01/2017	GW	125-11490	MASSIVE 19-8	PR

**General Comment:**

[Routine Inspection](#)

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Two track through pasture		
Corrective Action		Date:	

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Lease sign by metal shed		
Corrective Action:	Update to current operator	Date:	10/30/2020

<b>Emergency Contact Number:</b>			
Comment:			
Corrective Action:			Date: _____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	Metal panels around unit, wellhead, metal shed and VGS		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 1		
Comment:	Meter run in metal shed		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Churchill unit		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Arrow gas engine		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Telemetry equipment and gas scrubber		
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:	1-Vertical gas separator 50% buried by metal shed 1-Vertical gas separator in metal shed		
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 298821 Type: WELL API Number: 125-11490 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing. Casing production

Corrective Action: Last reported production was Aug 2019. Submit production reports for the last year

Date: 10/30/2020

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT