

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/29/2020

Submitted Date:

10/03/2020

Document Number:

701001436

**FIELD INSPECTION FORM**

Loc ID 321870 Inspector Name: Welsh, Brian On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 51065  
Name of Operator: LOEB LLC\* HERMAN L  
Address: P O BOX 838  
City: LAWRENCEVILLE State: IL Zip: 62439

**Findings:**

10 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Pelton, Shane	620-617-5870	shane@loeboil.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
208284	WELL	PR	01/08/2009	OW	017-07219	KRISS 2	PR

**General Comment:**

[Routine Inspection](#)

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Gravel road through farm ground		
Corrective ActionL			Date:

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:			Date:

<b>Emergency Contact Number:</b>			
Comment:			
Corrective Action:			Date: _____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:			Date:
Type: Ancillary equipment	# 3		
Comment:	Electric panel, cathodic rectifier, phase convertor		
Corrective Action:			Date:
Type: Vertical Heater Treater	# 0		
Comment:	Removed from location		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:	Lufkin 320		
Corrective Action:			Date:

<b>Tanks and Berms:</b>					
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	0		STEEL AST		38.641420,-102.088270
Comment:	Removed from location				
Corrective Action:					Date:

<b>Paint</b>	
Condition	

Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0		Open Top		38.641420,-102.088270
Comment:				Removed from location	
Corrective Action:				Date:	

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	
Comment:	
Corrective Action:	Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 208284 Type: WELL API Number: 017-07219 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing. Central tank battery for (Kriss 2 & 3, Evans Q #2 & #4, Evans R #1) XXXX'  
NNE @

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT