

# *Inspection Photos*

*API#107-06142*

*Operator: Bayless*

*Insp#: 692402568*

*Insp Date: 9/25/2020*



Photo#1:  
Over view of Location from entry.

September 25, 2020





Photo#2:  
Weed growth on Cut Slope.

September 25, 2020



Photo#3:  
Weed growth on Cut Slope.

Inspection Photos: Bayless Elits-Bradley API#107-06142





Photo#4:  
View along revegetated Fill Slope.



Photo#5:  
Debris on East side of site.

September 25, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Bayless Elits-Bradley API#107-06142