

Inspection Photos

API#107-06231

Operator: Booco's

Insp#: 692402573

Insp Date: 9/25/2020



Photo#1:

Over view of Location from entry to North; note Houndstongue in foreground.

September 25, 2020



Photo#2:
Weed concerns at site.

September 25, 2020



Photo#3:
Old Operator sign on site.



Photo#4:
View along Cut Slope.

September 25, 2020



Photo#5:
Graveled pad remains.



Photo#6:
Anchors have not been removed.

September 25, 2020



Photo#7:
Anchors have not been removed.