



40.04912, -108.58408, 6802.7ft, 332°  
10/05/2020 01:15:11 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 1. Location.**

Calamity Ridge 14-15C-1N100    API: 05-103-10462  
Inspection: 700403761






**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 2. Meter building.**

Calamity Ridge 14-15C-1N100    API: 05-103-10462  
Inspection: 700403761



40.04905, -108.58408, 6819.0ft, 195°  
10/05/2020 01:22:49 PM











40.04912, -108.58408, 6802.7ft, 28°  
10/05/2020 01:14:32 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 5. Tank & culvert.**

Calamity Ridge 14-15C-1N100    API: 05-103-10462  
Inspection: 700403761





**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 6. Hose leaking gas.**

**Calamity Ridge 14-15C-1N100    API: 05-103-10462**  
**Inspection: 700403761**







40.0491, -108.58401, 6827.4ft, 353°  
10/05/2020 01:20:51 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 8. Tank.**

Calamity Ridge 14-15C-1N100    API: 05-103-10462  
Inspection: 700403761

















40.04912, -108.58408, 6802.7ft, 272°  
10/05/2020 01:02:31 PM

















40.04912, -108.58408, 6802.7ft, 120°  
10/05/2020 01:04:34 PM