

Inspection Photos

Location Name:

Guttersen D 04-69HZ Multi-Well Pad

Location ID: 424329



Photo #1 Well




Photo #2 Missing Variance Tag



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name:

Guttersen D 04-69HZ Multi-Well Pad

Location ID: 424329



Photo #3 Missing Variance Tag



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name:

Guttersen D 04-69HZ Multi-Well Pad

Location ID: 424329



Photo #4 Well



Photo #5 Variance Tag



Inspection Photos

Location Name:

Guttersen D 04-69HZ Multi-Well Pad

Location ID: 424329



Photo #6 Well



Photo #7 Variance Tag



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name:

Guttersen D 04-69HZ Multi-Well Pad

Location ID: 424329



Photo #8 Stained Soil



Photo #9 Stained Soil

Inspection Photos

Location Name:

Guttersen D 04-69HZ Multi-Well Pad

Location ID: 424329



Photo #10 Stained Soil

