

Inspection Photos  
Location Name: Ozbun 10-19  
Location ID: 331666



Photo 1 WH sign

Photo 2 WH



Inspection Photos  
Location Name: Ozbun 10-19  
Location ID: 331666



**Photo 5 Dead weeds around wellsite.**

**Photo 6 Dead weeds around ECD.**

**Inspection Photos**  
**Location Name: Ozbun 10-19**  
**Location ID: 331666**




**Photo 7 Gas Meter Runs are locked and inaccessible,  
Horizontal Heated Separator**

**Photo 8 Gas Meter Run.**

# Inspection Photos

Location Name: Ozbun 10-19  
Location ID: 331666



**Photo 9 card in meter house indicates current calibration**