

Inspection Photos

API: 071-07991

Operator: TIMBER CREEK OPERATING

Inspection Date: 10/1/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-07991 | Date: 10/1/2020

Inspection Photos



Photo 1. Facing southeast toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07991 | Date: 10/1/2020

Inspection Photos



Photo 2. Facing toward the production equipment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07991 | Date: 10/1/2020

Inspection Photos



Photo 3. 30 Barrel produced water tank.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07991 | Date: 10/1/2020

Inspection Photos



Photo 4. There is oil inside of produced water tank which is estimated to be 1/3 full. The hatch of the tank was opened and a stick was used to observe the liquid in the tank which shows the presence of oil inside of tank.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07991 | Date: 10/1/2020

Inspection Photos



Photo 5. There is oily waste around and in the engine skid.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07991 | Date: 10/1/2020

Inspection Photos



Photo 6. The engine skid is full of oil and there is saturated oil on the surface.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07991 | Date: 10/1/2020