



40.15029, -108.20373, 6300.0ft, 79°
10/06/2020 03:18:28 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.

Ant Hill 7-43

API: 05-103-10992

Inspection: 700403777



40.15029, -108.20373, 6300.0ft, 4°
10/06/2020 03:17:51 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Well.

Ant Hill 7-43

API: 05-103-10992

Inspection: 700403777



40.15029, -108.20373, 6300 0ft, 341°
10/06/2020 03:16:21 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 3. Separator.

Ant Hill 7-43

API: 05-103-10992

Inspection: 700403777



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 4. Building.

Ant Hill 7-43

API: 05-103-10992

Inspection: 700403777



40.15029, -108.20373, 6300.0ft, 50°
10/06/2020 03:17:01 PM