

Inspection Photos
Location Name: Kimball Creek Pad #23-4C-995
Location ID: #420164
Inspection Date: October 7, 2020



Photo #1 – Pad sign.



Photo #2 – View of tank battery from southwest.



Inspection Photos

Location Name: Kimball Creek Pad #23-4C-995

Location ID: #420164

Inspection Date: October 7, 2020



Photo #3 – Localized accumulation of oil-stained soil located between separators and tank battery.



Photo #4 – View of separators and day tank from west.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Kimball Creek Pad #23-4C-995

Location ID: #420164

Inspection Date: October 7, 2020



Photo #5 – View of wellheads and day tank from southwest.



Photo #6 – Localized accumulation of oily waste (stained gravel) located southeast of day tank.

Inspection Photos

Location Name: Kimball Creek Pad #23-4C-995

Location ID: #420164

Inspection Date: October 7, 2020




Photo #7 – Accumulation of fluids beneath chemical pump to wellhead. Operator was notified of potential leak via phone on 10/8/2020.