

Inspection Photos

API: 071-08459

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 10/8/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-08459 | Date: 10/8/2020

Inspection Photos



Photo 1. Facing west at the beginning of the access road. There is erosion occurring down the road directed toward the county road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08459 | Date: 10/8/2020

Inspection Photos



Photo 2. The culvert at the beginning of the road is filled in with sediment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08459 | Date: 10/8/2020

Inspection Photos



Photo 3. There is erosion occurring down the road. Stormwater is not properly diverted.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08459 | Date: 10/8/2020

Inspection Photos



Photo 4. There is erosion occurring down the road. Stormwater is not properly diverted toward the culvert. Culvert is filled in with sediment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08459 | Date: 10/8/2020

Inspection Photos



Photo 5. Well sign posted at meter shed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08459 | Date: 10/8/2020

Inspection Photos



Photo 6. Well is temporarily abandoned. Unused equipment and pipe risers need to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08459 | Date: 10/8/2020