

Inspection Photos

API: 071-08670

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 10/8/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-08670 | Date: 10/8/2020

Inspection Photos



Photo 1. Facing southwest along the access road. There is erosion occurring down the road directed toward the county road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08670 | Date: 10/8/2020

Inspection Photos



Photo 2. Facing west along the access road near the location. There is erosion occurring down the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08670 | Date: 10/8/2020

Inspection Photos



Photo 3. Well sign posted at meter shed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08670 | Date: 10/8/2020

Inspection Photos



Photo 4. Facing southwest.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08670 | Date: 10/8/2020

Inspection Photos



Photo 5. Facing northeast.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08670 | Date: 10/8/2020