

# Inspection Photos

API: 071-09064

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 10/8/2020



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-09064 | Date: 10/8/2020

## Inspection Photos



**Photo 1.** Facing west toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09064 | Date: 10/8/2020



## Inspection Photos



**Photo 2.** Well sign posted at meter shed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09064 | Date: 10/8/2020



## Inspection Photos



**Photo 3.** There is 3 unused risers that have not been removed per previous corrective action.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09064 | Date: 10/8/2020



## Inspection Photos



**Photo 4.** Pipe risers near well.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09064 | Date: 10/8/2020