

Inspection Photos
Location Name: Saratoga 44-3
Location ID: 313327



Photo 1. Overview of location taken facing north.



Photo 2. Access road overgrown.

