

Inspection Photos

10/02/2020

Operator: UTAH GAS OP LTD DBA UTAH GAS
CORP - 10539

Location ID: 322292
Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location ID: 322292



Photo 1: Photo taken from the west end of the Location, facing north. Photos 1-4 provide an overview of the Location from north, northeast, southeast to south. Photo show final reclamation activities, including but not limited to, removal of debris, surface equipment and remaining risers, recontour/regrade and replacement of topsoils, compaction alleviation, and revegetation activities, have not been conducted on the Location pursuant to 1004 rules.

Photo 2: See comments under photo 1.

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location ID: 322292



Photo 3: See comments under photo 1. Photo also shows surface equipment remaining on the Location.



Photo 4: See comments under photo 1. Photo also shows surface equipment remaining on the Location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location ID: 322292



Photo 5: Photo taken from the east end of the Location, facing north. See comments under photo 1.



Photo 6: Photo taken from the east end of the Location, facing east. Photo shows what appears to be metal corner fence-post braces, as t-posts. This is debris and needs to be removed.

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location ID: 322292



Photo 7: Photo taken from the northeast corner of the Location, facing south. See comments under photo 1.



Photo 8: Photo taken from the northeast corner of the Location, facing west. See comments under photo 1.