

Inspection Photos

Location Name: Pipeline incident @ 40.017527, -104.559386

Location ID: 440176



Pic 1 Stained soil, and gas venting from ground looking south.



Pic 2 Stained soil, and gas venting from ground looking south.

Inspection Photos

Location Name: Pipeline incident @ 40.017527, -104.559386

Location ID: 440176



Pic 3 Plugged and Abandoned wellsite with casing sticking out of ground API-05-123-10361 Cindy 23-28 HRM Resources. Directly north of incident area, gas meter run running north and south.



Pic 4 Stained soil, and venting gas from ground looking north.

Inspection Photos

Location Name: Pipeline incident @ 40.017527, -104.559386

Location ID: 440176



Pic 5 Looking north from Gas meter run.



Pic 6 Gas meter run with pipeline direction north, and south.

Inspection Photos

Location Name: Pipeline incident @ 40.017527, -104.559386

Location ID: 440176



Pic 7 Gas Meter run emergency # next to road.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources