

Inspection Photos

API: 071-08494

API: 071-08780

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 10/8/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08494 | Date: 10/8/2020

Inspection Photos



Photo 1. Facing north toward the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08494 | Date: 10/8/2020

Inspection Photos



Photo 1. Facing northeast. The access road has not been reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08494 | Date: 10/8/2020

Inspection Photos



Photo 3. Facing west along the access road. Erosion is occurring along the road. Stormwater is flowing over water bars.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08494 | Date: 10/8/2020

Inspection Photos



Photo 4. The access road has not been reclaimed and erosion is occurring.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08494 | Date: 10/8/2020

Inspection Photos



Photo 5. Facing southeast along the access road toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08494 | Date: 10/8/2020

Inspection Photos



Photo 6. The culvert is filled in with sediment at the location. Culverts have not been removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08494 | Date: 10/8/2020

Inspection Photos



Photo 7. Facing southwest toward the location. The location has not been recontoured and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08494 | Date: 10/8/2020

Inspection Photos



Photo 8. Facing southwest toward the location. The cut slope is is not stabilized and there are signs of erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08494 | Date: 10/8/2020

Inspection Photos



Photo 9. Facing north along the fill slope.



Inspection Photos



Photo 10. Facing northwest.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08494 | Date: 10/8/2020