

Inspection Photos

API#081-06940

Operator: Mull Drilling

Inspection Number: 692402563

Inspection Date: 9/24/20





Photo#1:
View to Northeast from access road entry off County Road 4.

September 24, 2020



Photo#2:
View to North over Location.

Photo#3:
View to North over Location.

September 24, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Mull Drilling PA State Avalanche API#081-06940



Photo#4:
Close up of vegetation and ground conditions .



Photo#5:
Close up of vegetation and ground conditions .

September 24, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Mull Drilling PA State Avalanche API#081-06940