

## Inspection Photos

Location Name: W R YOUNG CATTLE CO

Location ID: 322420 & Remediation Project Number: 9341

Inspection Date: September 29, 2020



Location sign.



Solar powered SVE system.



## Inspection Photos

Location Name: W R YOUNG CATTLE CO

Location ID: 322420 & Remediation Project Number: 9341

Inspection Date: September 29, 2020



**Solar powered SVE system.**



**SVE wells.**



## Inspection Photos

Location Name: W R YOUNG CATTLE CO

Location ID: 322420 & Remediation Project Number: 9341

Inspection Date: September 29, 2020



**SVE well attached to the SVE system.**



**Hole in the tank battery secondary containment structure (red area).**

