

BP L48 San Juan



V2 Compliance Follow Up Form

18157755452

Reference Number:

Form Name:

Submitter Name:

Submission Date:

Location:

20201007-18157755452

V2 Compliance Follow Up Form

Cole Nichols (colen@horizonenvservices.com) |

colen@horizonenvservices.com

Sep 17, 2020 3:28:34 PM MDT

91 S Skylane Dr, Durango, CO 81303, USA

Sep 17, 2020 3:27:06 PM MDT [[View Map](#)]

INFORMATION

Section 1

Name

colen@horizonenvservices.com

Date

Sep 17, 2020

Well Name

GEARHART GAS UNIT B 2

Select State

Colorado

Work type

COGCC Inspection AR

Action Complete

Seeding
Erosion Repairs
Spot seeding

Photo of first corrective action completed



**Completed work description Corrective
Action 1**

blanket

Photo of second corrective action completed**Completed work description of corrective
action 2**

planting and blanket

Photo of third corrective action completed**Completed work description of corrective
action 3**

blanket and planting

Photo of fourth corrective action completed



**Completed work description of corrective
action 4**

seeding, planting

Additional photos



Additional photos



Summary of all work completed

seeded and mulched/erosion blanket. planted shrubs.