

Inspection Photos

API#081-06615

Operator: JW

Inspection Number: 692402561

Inspection Date: 9/24/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to Southwest.

September 24, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: JW PA Sand Hills Fed API#081-06615



Photo#2:
Overview of Location to North.

September 24, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: JW PA Sand Hills Fed API#081-06615



Photo#3:
Riser; not removed.



Photo#4:
Access road, not re-claimed.

September 24, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: JW PA Sand Hills Fed API#081-06615