

Inspection Photos

API#081-06960

Operator: HRM Resources

Inspection Number: 692402559

Inspection Date: 9/24/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:

View into Location from reclaimed portion of access road to Northeast.

September 24, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: HRM Res PA Sand Hills Fed API#081-06960



Photo#2:
View over heavily grazed area of Location.



Photo#3:
View over heavily grazed area of Location.

September 24, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: HRM Res PA Sand Hills Fed API#081-06960



Photo#4:
Weedy portion of site; Russian and Scotch thistle.

September 24, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: HRM Res PA Sand Hills Fed API#081-06960



Photo#5:

Aerial view of Location; dotted arrow indicates un-reclaimed portion of access road on Fee Surface.

September 24, 2020