

Inspection Photos

Location Name: Bruegman South EG Pad /34-021HN

Location #: 435903



Photo #1

Bruegman South EG 34-021HN (05-123-38842)
Wellsite

Producing | PR



Photo #2

Bruegman South EG 34-022HN (05-123-38838)
Wellsite

Producing | PR

Inspection Photos

Location Name: Bruegman South EG Pad /34-021HN

Location #: 435903



Colorado Oil & Gas Conservation Commission
40.52356, -104.54436, 4765.4ft, 355°
10/12/2020 13:37:45

Photo #3

Bruegman South EG 34-024HC (05-123-38841)
Wellsite

Producing | PR



Colorado Oil & Gas Conservation Commission
40.52286, -104.54555, 4779.7ft, 17°
10/12/2020 14:43:33

Photo #4

Bruegman South EG 34-021HN, 34-022HN, 34-024HC
Battery site

Active

No Battery sign posted

No Emergency number posted at Battery