

# Inspection Photos

10/12/2020

Operator: CAERUS PICEANCE LLC # 10456

Location ID: 334128

Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
COGCC

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC # 10456  
Location ID: 334128



**Photo 1:** Photo taken from the south end of the Location, facing northwest. Photo provides an overview of the production areas.



**Photo 2:** Photo taken from the south end of the Location, facing north. Photo provides an overview of the production areas.





**Inspection Photos**  
**Operator Name: CAERUS PICEANCE LLC # 10456**  
**Location ID: 334128**



**Photo 3:** Photo taken from the northwest end of the Location, facing south/southeast. Photo shows areas of the pad that do not appear to be needed for production areas and should be considered for reclamation. However the current pad size and "areas needed for production operations" on the Location is not exceedingly unreasonable.



**Photo 4:** Photo shows wells on the Location.





Inspection Photos  
Operator Name: CAERUS PICEANCE LLC # 10456  
Location ID: 334128



**Photo 5:** 2016 Google Earth Aerial image. Photo shows Location (#334128), and access roads (red lines) requiring reclamation pursuant to COGCC 1004 requirements; Access roads are considered additional, unnecessary disturbances that do not comport with Rule 1002.e(4)

