

# Inspection Photos

10/12/2020

Operator: CAERUS PICEANCE LLC # 10456

Location ID: 334415

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC # 10456  
Location ID: 334415



**Photo 1:** Photo taken from the southwestern area of the Location, facing north. Photos 1-3 provide an overview of the Location from north, northeast to east.



**Photo 2:** See comments under photo 1.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC # 10456  
Location ID: 334415



**Photo 3** See comments under photo 1.



**Photo 4:** Photo shows wells on the Location.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC # 10456  
Location ID: 334415



**Photo 5:** Photo taken from the south end of the Location, facing southwest. Photo shows areas of the Location not needed for production activities that require reclamation.





Inspection Photos  
Operator Name: CAERUS PICEANCE LLC # 10456  
Location ID: 334415



**Photo 5:** 2016 Google Earth Aerial image. Photo shows approximate areas on the south end of the Location (red polygon) that are not needed for production activities and require reclamation. Additionally, there area also areas of the pad to the south and west of the wells that also do not appear to be needed for production activities and should be considered for reclamation, however these areas of the pad are not exceedingly unreasonable.

