

**Inspection Photos**  
**Location Name: SUCKLA-BROWN UNIT-61N67W**  
**Location ID: 318596**



**Photo 1 – Location sign**



**Photo 2 – Stained soil at load out**

**Inspection Photos**  
**Location Name: SUCKLA-BROWN UNIT-61N67W**  
**Location ID: 318596**



**Photo 3 – Area where stained soil was documented in FIR 699501738. Stained soil no longer visible; hydrocarbon odor was present.**