

Inspection Photos

Location Name: LARAMIE ENERGY LLC McDaniel /2-1 Pad

Location ID: 334353



Photo #2007 from entrance to location.



Photo #2008 from entrance to location.

Inspection Photos

Location Name: LARAMIE ENERGY LLC McDaniel /2-1 Pad

Location ID: 334353



Photo #2010 Waddle in sediment trap has deteriorated and become debris.



Photo #2011 Waddle in sediment trap has deteriorated and become debris.